



SL #136
JULY 1982

SERVICE BULLETIN

AMERICAN HONDA MOTOR CO., INC. MOTORCYCLE SERVICE DEPARTMENT

VF750 SABRE/MAGNA PRODUCT UPDATE

VF750 Service Bulletins 2, 3, 4 and 5 cover operations that must be performed on 1982 VF750 Sabre and Magna motorcycles and are to be considered collectively as a Product Update. However, some of the operations are to be performed on only one model or VIN range; please study each of the four Product Update Service Bulletins.

All customers who have already taken delivery of a 1982 Sabre or Magna will be sent a general letter (see attached sample) urging them to contact their nearest Honda dealer to make an appointment for the operations applicable to their motorcycle. Because of the several variables (model, VIN) the customer letter cannot specifically explain what will be done to a particular motorcycle. 1982 Sabres or Magnas not yet delivered to a customer will also require some of the operations as part of Set-up.

All VF750's delivered or yet to be delivered will require updating five pages of the owner's manual. As part of the same mailing as this Service Letter, there are twenty-five sets of owner's manual correction pages--one sheet corrects one manual, either Sabre or Magna. If this quantity is not enough, you may order more, free of charge, by calling the Service Publications office (the phone number is listed in this mailing's cover letter).

The second page of this letter is an overview of the Product Update operations and the units to which they apply. The overview has been designed as a "worksheet." It can be photo-copied and used by your Service Writer to assist in preparing the repair order and time estimate for a particular customer's VF750.

AMERICAN HONDA MOTOR CO., INC.
Service Communications

MSL 4588 8207

ROUTING:

COPY 1

COPY 2

☐ GENERAL MANAGER

☐ SALES DEPT.

☐ OFFICE FILE

☐ SERVICE MANAGER

☐ MECHANICS

☐ SHOP MANUAL

APPLICATION

OPERATION

BULLETIN

FLAT RATE

TOTAL TIME

☐ if Sabre	☐ Thru VIN 010063	Check final drive oil VF750 #2 0.3 Correct air cleaner #3 0.2 Adjust valves #4 1.5 Replace FOIL cable #5 -- Correct owner's manual --	} 2.0
	☐ VIN 010064 or over	Adjust valves VF750 #4 1.5 Correct owner's manual -- --	

MODEL _____

VIN _____

☐ if Magna	☐ Thru VIN 020492	Check final drive oil VF750 #2 0.3 Adjust valves #4 1.5 Correct owner's manual --	} 1.8
	☐ VIN 020493 or over	Adjust valves VF750 #4 1.5 Correct owner's manual -- --	