

PARTS' NEWS

PARTS DIVISION

1983 and 1984 VF700F / 750F CAMSHAFTS

This Parts News contains camshaft ordering and return information to support Service Bulletins VF700F #3 and VF750F #16.

PARTS ORDERING INFORMATION

Use the information below when ordering replacement camshafts for 1984 VF700's and 1983/84 VF750F's.

• New-Type VF700F Camshafts

Honda Code	Part Number	Description	Dealer Net
2055093	14111-MB2-691	Front Intake	28.34
2055119	14131-MB2-691	Front Exhaust	
2055101	14121-MB2-691	Rear Intake	
2055127	14141-MB2-691	Rear Exhaust	

• New-Type VF750F Camshafts

Honda Code	Part Number	Description	Dealer Net
2055051	14111-MB2-305	Front Intake	28.34
2055077	14131-MB2-305	Front Exhaust	
2055069	14121-MB2-305	Rear Intake	
2055085	14141-MB2-305	Rear Exhaust	

PARTS RETURN INFORMATION

If your inventory contains any of the affected camshafts listed below or on the back of this Parts News, please return them to American Honda for credit. Follow the return procedure detailed on the back of this page.

• Affected VF700F Camshafts

Honda Code	Part Number	Description	Dealer Net
1782903	14111-MB2-690	Front Intake	28.34
1782911	14131-MB2-690	Front Exhaust	
1791888	14121-MB2-690	Rear Intake	
1782929	14141-MB2-690	Rear Exhaust	

MODEL

VF700F
VF750F

APPLICATIO

1983 — A/
1984 — A/

FILE UNDEF

Procedura

BULLETIN N

M850627

ISSUE DAT

6-27-85

(over)

MPN 9019 (8506)

ATS RETURN INFORMATION (continued)

Affected VF750F Camshafts

Honda Code	Part Number	Description	Dealer Net
1696954	14111-MB2-020	Front Intake	28.34
1512912	14111-MB2-010	Front Intake	
1426733	14111-MB2-000	Front Intake	
1696962	14131-MB2-020	Front Exhaust	
1512938	14131-MB2-010	Front Exhaust	
1426758	14131-MB2-000	Front Exhaust	
1538974	14121-MB2-020	Rear Intake	36.40
1512920	14121-MB2-010	Rear Intake	
1426741	14121-MB2-000	Rear Intake	28.34
1539006	14141-MB2-020	Rear Exhaust	
1512946	14141-MB2-010	Rear Exhaust	36.40
1426766	14141-MB2-000	Rear Exhaust	28.34

Return Procedure

A. Fill out and submit an O.A.R. to your assigned Parts Center.

1. Use Reason Code "S", and enter "000000000000" in the area normally reserved for the Shipper Number.

2. Write "VF Camshaft" in the Remarks Section.

3. No Shipment Listing or Invoice is required for this return.

B. After you receive your Authorized Return Documents, ship the items to the indicated Parts Center, freight prepaid.

1. Credit for each authorized return will be issued to you in the amount of current dealer net plus return freight.

Should you require further information, please contact your assigned Parts Center.

AMERICAN HONDA MOTOR CO., INC.
Parts Division