

HONDA

AMERICAN HONDA MOTOR CO., INC.
P.O. BOX 50 - 100 W. ALONDRA BLVD., GARDENA, CALIF. 90247
CABLE ADDRESS - AMEHON, GARDENA, CALIF. (213) 327 - 8280

July 14, 1982

Subject: VF750C/VF750S Carburetor Replacement Authorization

Dear Honda Motorcycle Dealer:

Proper repair procedure requires that carburetor replacement should be considered only after normal troubleshooting, adjustment, and repair have been attempted. Effective immediately, service authorization by a District Service Manager will be required for any warranty replacement of VF750C Magna or VF750S Sabre carburetors.

When you receive authorization, enter the authorization number on the warranty claim form, and attach the service authorization form if applicable. Send the carburetor(s), together with the warranty claim directly to:

AMERICAN HONDA MOTOR CO., INC.
Attn: Motorcycle Warranty Parts Inspection
100 West Alondra Boulevard
Gardena, California 90247

Sincerely,



Clinton Johnson
Warranty Supervisor